		GOODWILL AUTO AUCT	ION JANUARY 24, 2015
SEQ#	VEH#	OFFICE WAREHOUSE	VEHICLE INFORMATION PER DONOR
1	1588	2002 Ford Taurus 187.632	NO INFO
2	1564	1999 Isuzu Amigo 151.978	MAY NEED ALTERNATOR HAS BEEN SITTING
3	1550	2004 Buick LeSabre 105.178	WELL MAINTAINED NO KNOWN ISSUES GOOD TIRES DENTS IN R SIDE
4	1455	1999 Ford Expedition 237.152	BURNS OIL
5	1543	2001 Olds Silhouette 256.802	LEAKS
6	1555	2003 Ford Taurus 190.352	BELTS ARE GOING
7	1479	1999 Honda Accord 184.392	4 NEW TIRES POWER STEERING LEAKS BAD AXLE SEALS TRANS MAY BE GOING
8	1444	1993 Ford F150 128.216	RUNS WELL LEAK IN F BRAKE LINE BRAKE CABLE FOR PARKING BRAKE IS BROKEN
SEQ#	VEH#	ROW ONE	VEHICLE INFORMATION PER DONOR
9	1523	1978 Ford Mustang 83.557	GARAGED FOR MANY YEARS - FUEL PUMP IS OUT - GAS GAUGE DOES NOT WORK
10	1545	2002 Ford Windstar 144.467	RUNS BUT NOT ROADWORTHY - HAS A LIFT
11	1493	2000 Ford Taurus 170.480	NOT TURNING OVER
12	1500	2006 Ford 500 112.043	TRANSMISSION OUT
13	1525	2003 Hyundai Sonata 142.289	BLEW ENGINE ROD
14	1499	1999 Volkswagen Jetta 157.854	DOESN'T KNOW WHY IT'S NOT RUNNING
15	1492	2003 Acura MDX 196.867	RADIATOR AND TRANS LEAKS NEWER TIRES
16	1464	1990 Lexus LS4 213.015	DEAD BATTERY SITTING ALMOST A AYEAR
SEQ#	VEH#	ROW TWO	VEHICLE INFORMATION PER DONOR
	1458	1997 Lexus ES300 147.799	SITTING 1 YR MAY NEED CATALYTIC CONVERTER
	1458 1507	1997 Lexus ES300 147.799 2003 Saturn SL2 189.299	
17 18		2003 Saturn SL2 189.299	SITTING 1 YR MAY NEED CATALYTIC CONVERTER
17 18	1507	2003 Saturn SL2 189.299	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM
17 18 19	1507 1482	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS
17 18 19 20 21	1507 1482 1502	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY
17 18 19 20 21	1507 1482 1502 1534	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872 ROW THREE	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY NEEDS 3 CYL. REPLACED AND CONVERTER
17 18 19 20 21 SEQ#	1507 1482 1502 1534 VEH#	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872 ROW THREE	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY NEEDS 3 CYL. REPLACED AND CONVERTER VEHICLE INFORMATION PER DONOR OIL LEAKED OUT AFTER OIL CHANGE AND DRIVEN
17 18 19 20 21 seq#	1507 1482 1502 1534 VEH # 1486	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872 ROW THREE 2006 Mazda 6 84.002 1991 Mercedes 420SEL 152.093 OD	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY NEEDS 3 CYL. REPLACED AND CONVERTER VEHICLE INFORMATION PER DONOR OIL LEAKED OUT AFTER OIL CHANGE AND DRIVEN WITHOUT OIL
17 18 19 20 21 seq # 22	1507 1482 1502 1534 VEH # 1486 1509	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872 ROW THREE 2006 Mazda 6 84.002 1991 Mercedes 420SEL 152.093 OD	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY NEEDS 3 CYL. REPLACED AND CONVERTER VEHICLE INFORMATION PER DONOR OIL LEAKED OUT AFTER OIL CHANGE AND DRIVEN WITHOUT OIL SPEEDOMETER NOT WORKING
17 18 19 20 21 SEQ # 22 23 24 25	1507 1482 1502 1534 VEH # 1486 1509 1478	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872 ROW THREE 2006 Mazda 6 84.002 1991 Mercedes 420SEL 152.093 OD 1991 Toyota Celica 179.779 2002 Chevrolet Malibu 160.478	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY NEEDS 3 CYL. REPLACED AND CONVERTER VEHICLE INFORMATION PER DONOR OIL LEAKED OUT AFTER OIL CHANGE AND DRIVEN WITHOUT OIL SPEEDOMETER NOT WORKING WILL RUN WITH BATTERY 1 TIRES LOSING AIR
17 18 19 20 21 SEQ # 22 23 24 25	1507 1482 1502 1534 VEH # 1486 1509 1478 1520	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872 ROW THREE 2006 Mazda 6 84.002 1991 Mercedes 420SEL 152.093 OD 1991 Toyota Celica 179.779 2002 Chevrolet Malibu 160.478 ROW FOUR	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY NEEDS 3 CYL. REPLACED AND CONVERTER VEHICLE INFORMATION PER DONOR OIL LEAKED OUT AFTER OIL CHANGE AND DRIVEN WITHOUT OIL SPEEDOMETER NOT WORKING WILL RUN WITH BATTERY 1 TIRES LOSING AIR BAD FUEL PUMP
17 18 19 20 21 SEQ# 22 23 24 25 SEQ#	1507 1482 1502 1534 VEH # 1486 1509 1478 1520 VEH #	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872 ROW THREE 2006 Mazda 6 84.002 1991 Mercedes 420SEL 152.093 OD 1991 Toyota Celica 179.779 2002 Chevrolet Malibu 160.478 ROW FOUR	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY NEEDS 3 CYL. REPLACED AND CONVERTER VEHICLE INFORMATION PER DONOR OIL LEAKED OUT AFTER OIL CHANGE AND DRIVEN WITHOUT OIL SPEEDOMETER NOT WORKING WILL RUN WITH BATTERY 1 TIRES LOSING AIR BAD FUEL PUMP VEHICLE INFORMATION PER DONOR NEEDS A BATTERY; RADIO DOESN'T WORK; TRUNK
17 18 19 20 21 SEQ# 22 23 24 25 SEQ#	1507 1482 1502 1534 VEH # 1486 1509 1478 1520 VEH # 1506	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872 ROW THREE 2006 Mazda 6 84.002 1991 Mercedes 420SEL 152.093 OD 1991 Toyota Celica 179.779 2002 Chevrolet Malibu 160.478 ROW FOUR 1986 Cadillac Eldorado 171.759 2000 Buick LeSabre 144.609	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY NEEDS 3 CYL. REPLACED AND CONVERTER VEHICLE INFORMATION PER DONOR OIL LEAKED OUT AFTER OIL CHANGE AND DRIVEN WITHOUT OIL SPEEDOMETER NOT WORKING WILL RUN WITH BATTERY 1 TIRES LOSING AIR BAD FUEL PUMP VEHICLE INFORMATION PER DONOR NEEDS A BATTERY; RADIO DOESN'T WORK; TRUNK DOESN'T CLOSE; NOT RUNNING BAD WINDOW REGULATER ON PASS. SIDE NO
17 18 19 20 21 SEQ# 22 23 24 25 SEQ# 26	1507 1482 1502 1534 VEH # 1486 1509 1478 1520 VEH # 1506 1511	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872 ROW THREE 2006 Mazda 6 84.002 1991 Mercedes 420SEL 152.093 OD 1991 Toyota Celica 179.779 2002 Chevrolet Malibu 160.478 ROW FOUR 1986 Cadillac Eldorado 171.759 2000 Buick LeSabre 144.609 1998 Chevrolet Lumina 108.881	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY NEEDS 3 CYL. REPLACED AND CONVERTER VEHICLE INFORMATION PER DONOR OIL LEAKED OUT AFTER OIL CHANGE AND DRIVEN WITHOUT OIL SPEEDOMETER NOT WORKING WILL RUN WITH BATTERY 1 TIRES LOSING AIR BAD FUEL PUMP VEHICLE INFORMATION PER DONOR NEEDS A BATTERY; RADIO DOESN'T WORK; TRUNK DOESN'T CLOSE; NOT RUNNING BAD WINDOW REGULATER ON PASS. SIDE NO OTHER KNOWN ISSUES
17 18 19 20 21 SEQ# 22 23 24 25 SEQ# 26 27	1507 1482 1502 1534 VEH # 1486 1509 1478 1520 VEH # 1506 1511 1494 1508 1306	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872 ROW THREE 2006 Mazda 6 84.002 1991 Mercedes 420SEL 152.093 OD 1991 Toyota Celica 179.779 2002 Chevrolet Malibu 160.478 ROW FOUR 1986 Cadillac Eldorado 171.759 2000 Buick LeSabre 144.609 1998 Chevrolet Lumina 108.881 1977 Cadillac Deville 12.652 OD 1997 Ford Expedition 177.874	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY NEEDS 3 CYL. REPLACED AND CONVERTER VEHICLE INFORMATION PER DONOR OIL LEAKED OUT AFTER OIL CHANGE AND DRIVEN WITHOUT OIL SPEEDOMETER NOT WORKING WILL RUN WITH BATTERY 1 TIRES LOSING AIR BAD FUEL PUMP VEHICLE INFORMATION PER DONOR NEEDS A BATTERY; RADIO DOESN'T WORK; TRUNK DOESN'T CLOSE; NOT RUNNING BAD WINDOW REGULATER ON PASS. SIDE NO OTHER KNOWN ISSUES ENGINE CAM SHAFT BATTERY STARTS BUT BRAKE LINE WENT OUT - MOON ROOF WON'T CLOSE
17 18 19 20 21 seq # 22 23 24 25 seq # 26 27 28 29 30	1507 1482 1502 1534 VEH # 1486 1509 1478 1520 VEH # 1506 1511 1494 1508 1306	2003 Saturn SL2 189.299 1995 BMW 525i 133.032 1995 Buick LeSabre 182.053 2001 Mazda MPV 139.872 ROW THREE 2006 Mazda 6 84.002 1991 Mercedes 420SEL 152.093 OD 1991 Toyota Celica 179.779 2002 Chevrolet Malibu 160.478 ROW FOUR 1986 Cadillac Eldorado 171.759 2000 Buick LeSabre 144.609 1998 Chevrolet Lumina 108.881 1977 Cadillac Deville 12.652 OD	SITTING 1 YR MAY NEED CATALYTIC CONVERTER WON'T START - IGNITION PROBLEM DEAD BATTERY; SITTING 2 YEARS NEEDS A BATTERY NEEDS 3 CYL. REPLACED AND CONVERTER VEHICLE INFORMATION PER DONOR OIL LEAKED OUT AFTER OIL CHANGE AND DRIVEN WITHOUT OIL SPEEDOMETER NOT WORKING WILL RUN WITH BATTERY 1 TIRES LOSING AIR BAD FUEL PUMP VEHICLE INFORMATION PER DONOR NEEDS A BATTERY; RADIO DOESN'T WORK; TRUNK DOESN'T CLOSE; NOT RUNNING BAD WINDOW REGULATER ON PASS. SIDE NO OTHER KNOWN ISSUES ENGINE CAM SHAFT BATTERY STARTS BUT BRAKE LINE WENT OUT - MOON ROOF