



**Community Car Care Inc.**  
 1047 Perkins Drive  
 Kentucky, 41001. Alexandria  
 Phone: 859-635-1788 Fax: 859-635-1810  
 Making the world a better place one car at a time!

**INVOICE**

**111061**

Org. Est. # 097281  
 FED 61-1148989  
 KY 048906

**INVOICE**

Work Completed Date : 03/19/2015

Print Date: 03/26/2015

**COMMUNITY CAR CARE**

2002 Honda - Accord EX - 3L, V6 (183CI)

Lic # : - 41001

Odometer In : 0

Odometer Out : 182378

VIN # : 1HGCG2254 2A010414

Cust ID : 9660

Part Description	Qty	Sale	Ext	Labor Description	Extended
MOTOR MOUNT	1.00	85.56	85.56	REPLACE FRONT CALIPERS AND HOSES	71.18
TIMING BELT	1.00	43.70	43.70	REPLACE FRONT BRAKES	85.41
WATER PUMP	1.00	128.93	128.93	REPLACE REAR BRAKES	85.41
V-BELT	1.00	25.09	25.09	REPLACE TRANS - Remove & Replace - V6	709.85
V-BELT	1.00	32.07	32.07	STRUT ASSEMBLY - Removal & Installation - [DOES NOT include disassemble or align.] - Both	187.90
TIMING BELT TENSIONER	1.00	139.53	139.53	STRUT ASSEMBLY - Removal & Installation - [DOES NOT include disassemble or align.] - Both	156.58
SPARK PLUG	6.00	6.87	41.22	STABILIZER BAR CONTROL LINK - Remove & Replace - Both	62.63
AIR FILTER	1.00	19.15	19.15	WATER PUMP - Remove & Replace - [Includes: Bleed cooling system.] - V6 - w/Air Cond	501.07
FRONT ROTOR	2.00	48.58	97.16	FLUSH BRAKE SYSTEM	69.32
FRONT PADS	1.00	81.37	81.37	FLUSH POWER STEERING SYSTEM	39.86
CALIPERS	2.00	94.29	188.58	Replace worn wiper blades	0.00
BRAKE HOSE	1.00	64.63	64.63	Remove and replace worn wiper blades with new wiper blades.	
BRAKE HOSE	1.00	59.97	59.97	REPLACE AIR FILTER	0.00
REAR ROTOR	2.00	41.37	82.74	STABILIZER LINK - Remove & Replace - Both	62.63
REAR PADS	1.00	81.37	81.37	BALL JOINT - Remove & Replace - [DOES NOT include alignment.] - Lower,Each	208.78
BALL JOINT	2.00	62.53	125.06	SPARK PLUGS - Remove & Replace - V6	104.39
SWAY BAR LINK	2.00	39.05	78.10	Replace worn wiper blades	0.00
SWAY BAR LINK	2.00	46.02	92.04	Remove and replace worn wiper blades with new wiper blades.	
STRONG ARM	2.00	57.65	115.30	REPLACE HOOD SHOCKS	47.45
BATTERY	1.00	112.04	112.04	REPLACE BATTERY	23.73
EXHAUST CONNECTOR	1.00	11.06	11.06	COMPUTER WHEEL BALANCE	40.00
STRUT	2.00	280.36	560.72	TIRE PROTECTION PLAN	39.80
STRUT	2.00	236.68	473.36	ALTERNATOR ASSEMBLY - Remove & Replace - V6	125.27
ANCO 31 SERIES WIPER	2.00	14.95	29.90	WHEEL SPEED ABS SENSOR - Remove & Replace - One	52.20
SYNPOWER BRAKE FLUSH SERVICE	1.00	30.63	30.63		
VALVOLINE P/S FLUSH KIT	1.00	59.95	59.95		
USED TRANSMISSION	1.00	1100.00	1100.00		
CAP	4.00	14.05	56.20		
Tire Disposal Fee	4.00	3.00	12.00		
P205/60R16 91H BW FST FR710	4.00	91.96	367.84		
WHEEL SPEED SENSOR	1.00	123.27	123.27		
WHEEL LUG NUTS	20.00	7.60	152.00		
ALTERNATOR	1.00	251.83	251.83		
Job Supplies			39.63		



**Community Car Care Inc.**  
1047 Perkins Drive  
Kentucky, 41001. Alexandria  
Phone: 859-635-1788 Fax: 859-635-1810  
Making the world a better place one car at a time!

**INVOICE**

**111061**

Org. Est. # 097281  
FED 61-1148989  
KY 048906

**INVOICE**

Work Completed Date : 03/19/2015

Print Date: 03/26/2015

COMMUNITY CAR CARE

2002 Honda - Accord EX - 3L, V6 (183CI)

Lic # : - 41001

Odometer In : 0

Odometer Out : 182378

VIN # : 1HGCG2254 2A010414

Cust ID : 9660

Part Description	Qty	Sale	Ext	Labor Description	Extended
------------------	-----	------	-----	-------------------	----------

[ Payments - ]

*Thank you for your trust.*

An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. All Parts are New unless otherwise designated. Warranty on parts and labor is two years unlimited miles applies to new parts only. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Labor:	2,633.66
Parts:	4,962.00
Sublet:	39.80
Sub:	7,635.46
Tax:	297.72
Total:	\$7,933.18
Bal Due:	\$7,933.18

Signature \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_