

## GOODWILL AUTO AUCTION MARCH 23, 2019

| SEQ # | VEH # | OFFICE WAREHOUSE                        | VEHICLE INFORMATION PER DONOR  |
|-------|-------|---|--|
| 1     | 165   | 1998 Saturn SL2 215.375                 | IGNITION LOCK STICKS. NEEDS A NEW MUFFLER  |
| 2     | 178   | 2007 Chevy Cobalt 137.758 OD <b>RBS</b> | REBUILT SALVAGE - NO KNOWN ISSUES  |
| 3     | 187   | 2002 Ford Mustang 087.544 <b>RBS</b>    | REBUILT SALVAGE - RUNNING - NO KNOWN ISSUES  |
| 4     | 188   | 1998 Ford Explorer 178.163              | NO INFO  |
| 5     | 171   | 2004 Toyota Camry Solara 185.206        | NO INFO  |
| SEQ # | VEH # | ROW ONE                                 | VEHICLE INFORMATION PER DONOR  |
| 6     | 123   | 2002 Chevy Avalanche 171.399            | DOESN'T RUN - MOTOR ISSUES   |
| 7     | 110   | 1998 Ford Ranger 190.681                | RUSTING OUT UNDERNEATH. ENGINE RUNS WELL   |
| 8     | 122   | 2002 Saturn SL2 187.402                 | VEHICLE JUST STOPPED RUNNING. MECHANIC THINKS IT'S THE TIMING CHAIN  |
| 9     | 103   | 2001 Buick Regal 1 OD                   | BODY DAMAGE ON FRONT RIGHT QUARTER PANEL; POWER WINDOWS DON'T ALL WORK; BATTERY MAY NEED JUMPED; DRIVES WELL |
| 10    | 236   | 2006 Ford E450 152.404                  | NEEDS A HEAD GASKET  |
| 11    | 212   | 2004 Internat'l 8600 Semi 134.419       | NO INFO  |
| 12    | 115   | 2005 GMC W3500 Box Truck 296.350        | DEAD BATTERY; TIRES NEED TO BE REPLACED; SAME WITH BRAKES; SEAL LEAK ALLOWS OIL TO GET INTO THE RADIATOR     |
| SEQ # | VEH # | ROW TWO                                 | VEHICLE INFORMATION PER DONOR  |
| 13    | 206   | 2007 Freightliner Sprinter 196.922      | RUNS, BUT HAS NO TURBO BOOST - WAS TOLD IT IS A WIRING PROBLEM; SOFT BRAKES                                  |
| 14    | 74    | 1997 Honda Civic 190.434                | NEEDS REAR BUMPER REATTACHED; RUNNING ROUGH (COIL PACKS?)  |
| 15    | 102   | 1989 Toyota Pickup 159.614 OD           | NEEDS A NEW SET OF TIRES; NO BATTERY - SHOULD STILL START IF YOU PUT A NEW ONE IN; MANUAL SHIFT              |
| 16    | 107   | 2007 Mazda 6 170.856                    | NO INFO  |
| 17    | 106   | 2004 Cadillac Deville 347.907           | WON'T START; HAS A BLOWN HEAD GASKET; NORSTAR ENGINE   |

**TURN OVER FOR MORE**

| SEQ #  | VEH # | INSIDE FENCE                       | VEHICLE INFORMATION PER DONOR  |
|--|-------|------------------------------------|--|
| 18   | 208   | 1984 Jayco 25' Motorhome 57.882    | DOES RUN   |
| 19   | 240   | 2003 Ford Explorer 182.793         | GOOD CAR, BUT AFTER PUTTING ALMOST \$2,000 INTO IT LAST YEAR, DECIDED TO DONATE IT BECAUSE IT NEEDS AN INTAKE MANIFOLD   |
| 20   | 6     | 2001 Hyundai Tiburon 157.179       | RUNS, BUT OVERHEATS; LOWER CONTROL ARM NEEDS TO BE REPLACED (PART INCLUDED); DEAD BATTERY  |
| 21   | 176   | 1991 Plymouth Voyager 230.059      | NEEDS BRAKE CALIPER - REBUILT TRANS  |
| 22   | 169   | 2005 Ford 500 81.426               | MAY NEED TRANSMISSION WORK   |
| 23   | 111   | 1998 Viking 24 Travel Trailer      | NO LEAKS. NEEDS NEW CRANK MECHANISM. NEEDS SPRINGS REPLACED  |
| SEQ #  | VEH # | ROW THREE                          | VEHICLE INFORMATION PER DONOR  |
| 24   | 114   | 1999 Saturn SL2 162.993 <b>RBS</b> | <b>**RBS**</b> - NEEDS A FUEL PUMP; OTHERWISE, IT'S A GOOD RELIABLE CAR; HAS NEW TIRES, A 2 1/2 YEAR OLD BATTERY; BURNS A QUART OF OIL EVERY 1000 MILES; WELL-MAINTAINED |
| 25   | 148   | 2005 Mercury Mountaineer 187.538   | DEAD BATTERY - FLAT TIRE - VERY LITTLE RUST. RUNS GREAT. A/C DOES NOT WORK   |
| 26   | 135   | 1992 Ford F150 127.617 OD          | HAS NOT RUN IN SEVERAL YEARS. BODY IN GOOD SHAPE. POSSIBLY NEEDS FUEL PUMP   |
| SEQ #  | VEH # | ROW FOUR                           | VEHICLE INFORMATION PER DONOR  |
| 27   | 120   | 1995 Chevy S10 302.593 <b>RBS</b>  | <b>*RBS*</b> - EXHAUST PROBLEMS-STARTED SMOKING; STOPPED RUNNING   |
| 28   | 129   | 1999 Ford E150 278.270 OD          | NEEDS A BATTERY; HOLE SOMEWHERE WHERE YOU PUT IN FUEL NOZZLE - NEEDS TO FILL UP SLOW OR IT LEAKS OUT   |
| 29   | 105   | 2007 Buick Rendezvous 233.677      | NEEDS A CATALYTIC CONVERTER AND BRAKE PADS   |
| <b>EML = EXCEEDS MECHANICAL LIMITS</b><br><b>RBS = REBUILT SALVAGE</b><br><b>OD = ODOMETER DISCREPANCY</b> |       |                                    | <b>GOODWILL AUTO AUCTION</b><br><b>DOES NOT GUARANTEE</b><br><b>THE ACCURACY OF THE INFORMATION LISTED ABOVE</b>   |